

#### **DEVELOPMENT PERMIT NO. DP000961**

# WESTERN FOREST PRODUCTS INC Name of Owner(s) of Land (Permittee)

#### 500 DUKE POINT HIGHWAY Civic Address

- 1. This development permit is issued subject to compliance with all of the bylaws of the municipality applicable thereto, except as specifically varied or supplemented by this permit.
- 2. This development permit applies to and only to those lands within the municipality described below, and any and all building structures and other developments thereon:

Legal Description:

LOT 23, SECTIONS 8 AND 9, DISTRICT LOTS 370 AND 429, NANAIMO DISTRICT, PLAN 37924

PID No. 001-038-095

3. The land described herein shall be developed strictly in accordance with the following terms and conditions and provisions of this permit and any plans and specifications hereto which shall form a part thereof.

Schedule A Location Plan

Schedule B Site Plan

Schedule C Office Building, Elevations

Schedule D Dry Shed, Plan & Schedules

Schedule E Package Outfeed Area, Plan & Elevation

Schedule F Maintenance Shop, Elevation & Floor Plan

Schedule G Archaeological Report

Schedule H Fence Details

- a) If the applicant does not substantially commence the development permitted by this permit within two years of the date of this permit, the permit shall lapse.
- 4. This permit is not a building permit nor does it constitute approval of any signage. Separate applications must be made for a building permit and sign permit.

REVIEWED AND APPROVED ON

016. FEB. 25

Date


D. Lindsay

Community Development

Pursuant to Section 154 (1)(b) of the Community Charter

GN/In

Prospero attachment: DP000961



**DEVELOPMENT PERMIT NO. DP000961** 



## **LOCATION PLAN**

**Subject** 


**Property** 


Civic: 500 Duke Point Highway
Lot 23, Sections 8 and 9, and District Lots 370 and 429,
Nanaimo District, Plan 37924


Development Permit DP000961 500 Duke Point Highway Schedule B

1/3

SITE PLAN








# Development Permit DP000961

Schedule C

500 Duke Point Highway

OFFICE BUILDING, Elevations





THIS DRAWING AND ALL THE DESIGNS
AND MODIFIED LIKENESSES THEREOF
ARE THE SOLE PROPERTY OF BRITCO.
AND MAY NOT BE REPRODUCED OR
SUBMITTED TO OUTSIDE PARTIES
WITHOUT THE EXPRESSED WRITTEN
CONSENT OF BRITCO.

DATE JULY 15/93	REVISIONS		DATE	ľ
SCALE 1/4" = 1'-0"	A	SENT FOR APPROVAL	311.16/33	
DRAWN BY CAB	В		JU 27/33	
CHECKED	1 0	REVISE PER 2 ND. PLR	ANGUAS	
P	D		Alisan/as	
J J93Ø172				
CAD REF.# J93172EL	_		-	

PROJECT TITLE
MAYO FOREST PRODUCTS
OFFICE COMPLEX
DRAWING TITLE
ELEVATIONS SHT.NO.









Development Permit DP000961 500 Duke Point Highway Schedule F

1/2

MAINTENANCE SHOP, Elevation & Floor Plan





ARCHAEOLOGICAL REPORT





556 Hurinston Avenue Courtenay B.C. 19N 2X5 Phone: (250) 897-3853 Fux: (250) 897-3389

October 28, 2015

Western Forest Products Inc. 510-700 West Georgia Street Vancouver, BC V7Y 1A1

Attn: Roy McCaig, General Manager, Capital Projects

Re: Archaeological Overview Assessment of WFP Duke Point Facility

This letter presents the results and recommendations of an archaeological overview assessment (AOA) conducted by Baseline Archaeological Services Ltd. (Baseline) of the Western Forest Products Inc. (WFP) industrial facility on Duke Point, Nanaimo, BC. The development includes upgrades to the antisapstain dip tanks and construction of new dry sheds, maintenance shop and office complex.

The work reported herein consists of an AOA and PFR as defined in the British Columbia Archaeological Impact Assessment Guidelines (1998). This report is concerned with identifying any known archaeological sites in conflict with the development area and making management recommendations on how to proceed in the event of archaeological materials being in conflict with proposed ground disturbing activities. It is also concerned with determining the potential for any unrecorded archaeological sites. This report does not address any First Nations traditional use activities and sites. As such, this report does not comprehensively document all First Nations interest in the land. The study was conducted without prejudice to First Nations treaty negotiations, aboriginal rights, or aboriginal title.

Archaeological sites are defined as locations which contain physical evidence of past human activity, such as artifacts or features. Archaeological remains which predate, or are likely to predate, 1846 are automatically protected from any form of alteration, excavation, damage or desecration in British Columbia under the *Heritage Conservation Act (HCA)*. Other sites protected under the *HCA* include aboriginal rock art sites with historical or archaeological value, burial places and heritage wrecks.

The AOA was initiated with a background file search of the Remote Access to Archaeological Data (RAAD) website. There are two archaeological sites recorded on the property: DgRx-5 and DgRx-10. Both sites were originally recorded in 1973 and 1975 as shell midden sites with additional archaeological excavations being conducted in DgRx-5 in 1979. DgRx-5 is located within the development footprint of the dry sheds and DgRx-10 is located to the south within the currently undeveloped portion of the property.

During a 1994 archaeological impact assessment for the Duke Point Ferry Terminal Highway Access (Millennia Research – Permit 1994-0144), numerous surrounding sites were revisited.

This included DgRx-5, which could not be relocated and was assumed to be completely destroyed by the development of the industrial property. DgRx-10 was not noted as being sought during this assessment.

A 2006 note by the BC Archaeology Branch on the DgRx-5 site inventory form confirms the 1994 assessment of being completely destroyed and the site has been assigned 'legacy' status. Legacy sites remain on the provincial data base but are no longer protected under the *HCA* and a permit is not required for development activities within the site boundary.

Additionally, the Lewkowich Engineering Associates Ltd. geotechnical assessment was reviewed during this AOA. Bore holes 15-04 and 15-05 were in the immediate vicinity of DgRx-5 and both bore logs indicate that the subsurface composition includes a sandy fill matrix to bedrock. The descriptions and photos do not indicate the presence of any archaeological shell midden material. The results of bore holes 15-01 to 15-03 had similar results.

Based on the results of the AOA, no further archaeological work is recommended for the developed (paved and built) portion of the property.

To note, DgRx-10 remains a protected archaeological site under the *HCA* and any land altering activities within the recorded site boundary must be conducted under a Section 12, Site Alteration Permit (SAP). Due to the significant disturbance to this area in general, an archaeological impact assessment would likely not be required by the Archaeology Branch prior to issuing a SAP.

Developers and operators should be made aware of the potential of undiscovered archaeological remains in any surveyed or unsurveyed areas. Archaeological resources are protected under the Heritage Conservation Act and if archaeological remains are encountered, all development activities in the vicinity of the archaeological remains must be halted so as not to threaten these remains, and the immediate notification of BC Archaeology Branch, Ministry of Forests, Lands and Natural Resource Operations must occur.

Please feel free to contact me if you have any questions or concerns.

Sincerely,

Chris Engisch, B.A., RPCA

Archaeologist




Figure 1. Location of Archaeological Sites

Schedule H

1/2

**FENCE DETAILS** 

### Mid-Island Fence Products

2565 McCullough Rd.
Nanaimo, B.C. V9S 4M9
Telephone (250) 741-1450 Fax (250) 741-8450
E-mail; midislandfence@shaw.ca

As per site visit, the specifications and cost of said fencing project would be as follows.

#### Existing Specifications -

1 5/8 commercial pipe toprail

1 7/8 commercial pipe line posts

2 7/8 commercial pipe terminal posts

6' high, 2"X9 gauge galvanized chain link

(3) strands of barbed wire on top of fence

9 gauge galvanized tension wire at bottom of fence

All posts set into concrete

#### Scope of Work -

### (Fence Repairs)

Straighten (6) leaning fence posts

Replace (5) damaged 1 7/8 line posts

Replace (1) damaged broken 2 7/8 terminal posts

Replace aprox. 50'-60' of damaged chain link fence mesh

Replace aprox. 30-40' of damaged 1 5/8 toprail

Replace aprox. 380' worth of missing fence ties

Replace any damaged or missing fence fittings

Replace or repair any damaged barbed wire

#### (Privacy Slats)

Supply and install aprox. 2116' of new "PDS" style privacy slats (in chosen colour) Slats to be install in existing 6' high chain link fence along Duke Point Hwy.

\*Please refer to the attached file to view an example of our "PDS" privacy slats

#### Cost -

A) The cost of the fence repairs after installation would be \$3,989.00 plus G.S.T.

