

NEWS RELEASE

Distributed April 14, 2015

Investigations concludes for two recent home fires

Summary

Fire Prevention Officers concluded their investigations into the Nicol Street and the 5th Street residential fires. In the Nicol Street fire on April 9th, it was determined that the fire started at the rear of the building in the exterior area of the stairs leading to the closed-in porch. Remnants of smoking materials were found in this area. The cause of the fire is undetermined however it is suspected that poorly discarded smoking materials ignited the fire which displaced 6 occupants. During the investigation it was determined that the smoke alarms were disabled or removed.

The 5th Street fire on April 11th revealed that the cause of the fire was an electrical power cord connected to a table lamp in one of the upper floor bedrooms. The smoke alarms activated and 10 people were displaced.

Strategic Link: The City of Nanaimo is committed to Public Safety.

Key Points

- Smoke alarms should never be disabled or removed due to false activations. Smoke alarms save lives.
- Make sure your power cords and plugs are in good condition.
- Make sure any electrical cords show no signs of wear and do not kink, twist or knot. Power cords should never be placed under furniture.
- For additional Fire and Life Safety Information visit fire.nanaimo.ca

Quotes

"Once again we want to remind residents to make sure they have working smoke alarms and ensure your electrical cords are in good shape. In a period of a few days we have seen 16 people displaced with no content insurance and having to start all over. "

Ennis Mond
Fire Prevention Officer
Nanaimo Fire Rescue

-30-

Contact:

Ennis Mond
Captain - Fire and Loss Prevention Division
Nanaimo Fire rescue
flpd@nanaimo.ca
250-755-4563



View the online edition for more information -
<http://cnan.ca/1CXBSHx>